

# LeanNET® File Manager

For all your interface needs



**Rules**

Name	Type	Description	GED Filter	Input Directory	Output Location
<input checked="" type="checkbox"/> GED Glass Routing	GED Task	Routes specified GED	None	D:\Jobs\AtriumNC\GEDSCH	D:\Jobs\AtriumNC\GED Cutter\
<input checked="" type="checkbox"/> Hegla Glass Routing	GED Task	Routes GED Schedule	None	D:\Jobs\AtriumNC\GEDSCH	D:\Jobs\AtriumNC\Hegla Cutter\
<input checked="" type="checkbox"/> Lisc Glass Routing	GED Task	Routes selected GED	Xfer Only WinIG S	D:\Jobs\AtriumNC\GEDSCH	D:\Jobs\AtriumNC\Lisc Cutter\
<input checked="" type="checkbox"/> IGUnitLabel	Report	Labels for Production	None	C:\Jordan TN\GEDSCH\	Use Report Printer
<input checked="" type="checkbox"/> Convert GED to Merge	GED Task	Creates a merge file	None	D:\Jobs\Silverline\GEDSCH\	D:\Jobs\Silverline\WinIGImport\
<input checked="" type="checkbox"/> Stock Glass Process	GED Task	Process Cut or Stock	None	D:\Jobs\SL_Dallas\DL\	D:\Jobs\SL_Dallas\ProcessedDL\
<input checked="" type="checkbox"/> No Header Purchase Glass R	Report	Print No Report head	None	D:\Jobs\Jordan TN\GEDSCH	Use Report Printer
<input checked="" type="checkbox"/> Copy Only Tempering Sch	GED Task	Copies Only TemperS	TemperSchOnly	D:\Jobs\ViWinco\ViWincoS	D:\Jobs\ViWinco\TemperSchs\
<input checked="" type="checkbox"/> GOD PreRel File Routing	GED Task	Routes Files to a diffe	None	D:\Jobs\Silverline\GEDSCH\	D:\Jobs\Silverline\GODPreRel\
<input checked="" type="checkbox"/> Split Lt MasterMerge	GED Task	Splits ASCII Master M	None	D:\Jobs\Silverline\MasterM	D:\Jobs\Silverline\SplitMerges\
<input checked="" type="checkbox"/> NoHeadingPatternFile	Report	PatternReportFile wit	None	D:\Jobs\Jordan TN\GEDSCH	Use Report Printer
<input checked="" type="checkbox"/> Pattern Summary Report	Report	Prints Pattern Summ	None	X:\GlenowOptTests\Glenow	HP LaserJet 4P
<input checked="" type="checkbox"/> Production Batch Report	Report	Prints Production Bat	None	D:\Jobs\SimiValley\200 Lite	\\F117\03CorpKonica_PS
<input checked="" type="checkbox"/> RelToOptServer	GED Task	Routes Files from Wir	None	D:\Jobs\Silverline\GEDSCH\	X:\Silverline\GEDSCH\
<input checked="" type="checkbox"/> GOD DB Import	GED Task	Imports PreRel Schec	None	D:\Jobs\Silverline\GEDSCH\	D:\Jobs\Silverline\GODPreRel\

**Interval**  
Minutes: 0  
Seconds: 10

**Service**

**Output**  
Printer: Use Report Printer  
Output Directory: [Browse]  
Options:  Print  Preview  Collate  RTF  
 PDF  HTML  Excel  Text

**Input**  
File Source Directory: [Browse]  
Processing Options:  Apply Filter  Include Merge Files

**GED File Filter ... Integrated Development Environment**

**LeanNET File Mgr System Setup**

**File Purging**

**Options**  
File Filter: [Select]  
Run Interval: [Select] minutes  
Purge File: [Select] seconds  
Log Level:  None  Basic  Detailed  
 No Warning Messages

**Administrator**  
Login: [Text]  
Password: [Text]  
Log Out  
Save Cancel

## FEATURES

- ▶ Simple rules based setup. External machines, Reports / Labels and GED file conversions are simple and easy to setup and configure.
- ▶ Individual "Rule Management", allows unparalleled flexibility.
- ▶ GED's "Hide" feature, automates rule processing without cluttering the desk top.
- ▶ GEDs Customer Specific "Task" dlls and GED Report and Label templates.



## BENEFITS

- ▶ Easy Integration and Setup. Individual rules allow customer selectivity for file, machine interfaces and Report and Label Generation.
- ▶ Adaptable; each rule can be specifically tailored to meet processing rules and interface constraints and formats.
- ▶ Simplifies Operation; GED's "Hide" process allows File Manager to automatically process selected rules while staying out of the way of other applications.
- ▶ Improves Process Integration. One application now provides standard and custom interface solutions for machinery and Report / Label generation along with Electronic File Generation.

GIVING YOU GREATER CONTROL THAN EVER BEFORE

# LeanNET® File Manager

Consider GED for all your needs



Glass Fabrication

IG Spacer Fabrication

Glass Cutting & Loading

Glass Washing

Muntin Fabrication

Screen Systems

Decorative Glass Solutions

Window Fabrication

Cutting

Fabrication

Welding

I-3 SmartLoad Welding System

Cleaning

Automated Systems

Software Process Solutions

Material Handling Solutions

Training & Support

Special Systems

## SPECIFICATIONS:

### LeanNET® FileMgr

Windows XP Pro SP3, 1 G RAM;  
100 G Hard Drive

### Compatible GED Machinery:

All GED Equipment

Supports customized interface solutions for non GED equipment and special processes.

Compatible with LeanNET Report and Label Designer templates

Cart 1 Inspection Tst IG Cart Summary Report

Seq	Tracking	Description	Width	Height	Spacer	Gas	Mounts	Picture
1	1473373.007.001.1.1	SS LOW E / SS CLEAR	31 7/8	31 7/8	13/32		21143CHWHITE CONTOUR MUNTIN	
2	1474026.007.001.1.1	SS CLEAR / SS CLEAR	19 3/4	19 3/4	3/8		21143CH1316 GREEN FLAT MUNTIN	
3	1472966.001.001.1.1	SS LOW E / SS CLEAR	25	32 1/2	13/32		21143CHWHITE CONTOUR MUNTIN	
4	1540421.001.001.1.1	SS LOW E / SS CLEAR	39 1/16	38 1/2	13/32		21143CHWHITE CONTOUR MUNTIN	
5	1474026.004.001.1.1	SS CLEAR / SS CLEAR	31 3/4	55 3/4	3/8		21143CH1316 WHITE FLAT MUNTIN	
6	1472966.001.001.1.1	SS LOW E / SS CLEAR	45	32 1/2	13/32		21143CHWHITE CONTOUR MUNTIN	
7	1567068.001.001.1.1	SS LOW E / SS CLEAR	32	48	11/32		21143CHDEE GOLD BARKLEY GLASS	



To learn more, call 330.963.5401, fax 330.963.0584 or visit us at [www.gedusa.com](http://www.gedusa.com)

